




NOTE:


1. ALL G.I PIPE SHOULD BE S40 AND ITS UPPERTINANCES LIKE POST CUP, BARBED WIRE HOLDERS, ETC..
2. ALL TURN BUCKLES, STRETCHER BAND & FLAT BAR, TRUSS ROD, BARBED WIRE SHOULD BE HOT DIPPED GALVANIZED TOO INCLUDING TENSION WIRES.




 **TYP. CORNER AND LINE POST DETAIL**



ACCESS GATE DETAIL
N.T.S.



TOP/BOTTOM HINGE
N.T.S.



POST CAP DETAIL TYP.
N.T.S.

NOTE:

1. ALL G.I PIPE SHOULD BE S40 AND ITS UPPERTINANCES LIKE POST CUP, BARBED WIRE HOLDERS, ETC..
2. ALL TURN BUCKLES, STRETCHER BAND & FLAT BAR, TRUSS ROD, BARBED WIRE SHOULD BE HOT DIPPED GALVANIZED TOO INCLUDING TENSION WIRES.